

PTSG restores the façade of a major hotel



PTSG restores the façade of a major hotel



PTSG Building Access Specialists Ltd is one of the five specialist business divisions within Premier Technical Services Group Ltd (PTSG).

Its operatives are access specialists, trained in the use of rope access, mobile elevating platforms (MEWPs) and building maintenance units (BMUs) to reach all areas of buildings. This enables them to carry out a range of specialist services to ensure they remain in a first-class condition, complying with the latest regulations:

Cleaning

- Window cleaning
- Façade and cladding cleaning
- Gutter, fascia and soffit cleaning

Fabric Maintenance

- Roofing repairs
- Cladding, masonry and stonework repairs
- Window repairs and replacement
- Signage (repairs, installations and removals)
- Painting and decorating

Case study

PTSG Building Access Specialists Ltd recently completed a project in South London for a major customer in the hotel and hospitality industry.

The hotel is located in Battersea, close to Clapham Junction, Britain's busiest rail interchange. It's also close to the famous Battersea Power Station, which has undergone a dramatic transformation in recent years (PTSG's Electrical Services engineers delivered a new lightning protection system at the iconic structure).

PTSG excels in restoring buildings to a perfect condition, which can involve multiple specialist disciplines.

The façade of the hotel had clearly not been maintained on a regular basis and was looking tired and shabby. PTSG excels in restoring buildings to a perfect condition, which can involve multiple specialist disciplines.

The scope of work carried out by PTSG's high-level operatives work included cleaning the fabric of the building's exterior; repairs to masonry and plasterwork, some of which was crumbling and in a bad state of disrepair; and decorating work – painting the surfaces of the building after repairs had been completed.

The result was a fresh new appearance for the hotel, which can be glimpsed in photographs in this case study. Regular cleaning and maintenance from a specialist services provider like PTSG will ensure the façade of the hotel remains in an excellent condition.

